


# CV JOINT WITH HALFSHAFT



Key to figures: The first figure is the ft lb force necessary to break the CV Joint.

These have been tested at 30 degrees.

